

TED-DEE BEAR Septic

8905 NE 115 Street
VANCOUVER, WA 98662

360.896.5143
Fax: 360.896.2003

Mail To: Kayren Feinauer
13507 NE BETTS RD
VANCOUVER, WA
98686

PROPERTY INFORMATION

Location: 13507 NE BETTS RD
VANCOUVER
Tax ID: 186255000

Use:

GENERAL SYSTEM TYPE: Gravity system

ON ID: ON0037787

Fold
Here

ON-SITE WASTEWATER TREATMENT SYSTEM INSPECTION REPORT

Inspected: 03/09/2011 - Inspection Type: ROUTINE - Correction Status: No corrections needed

Company: Certification - Level 2
TED-DEE BEAR Septic

Work Performed By:
Ted Gibson

Submitted 03/16/2011 by:
Nathan Eterno

Fold
Here

COMMENTS & GENERAL INSPECTION NOTES

No Deficiencies Noted

riser lid 4" below grade - 3 ft round lid

GENERAL SITE & SYSTEM CONDITIONS

The General Site and System Conditions were:	Fully Inspected
All Components accessible for maintenance, secure and in good condition:	YES
Surfacing effluent from any component (including mound seepage):	NO
Components appear to be watertight - no visual leaks:	YES
Improper encroachment (roads, buildings, etc.) onto component(s):	NO
Component settling problems observed:	NO
Abnormal ponding present for one or more of the disposal components:	NO
Subsurface components adequately covered	YES
Site maintenance required (e.g. Landscape maintenance) If yes, describe in comments:	NO

ONSITE SEWAGE SYSTEM INSPECTION DETAIL

TANK: Septic Tank - 1 Compartment

This component was:	Fully Inspected	
Component appears to be functioning as intended:	YES	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Effluent Filter Cleaned (N/A = Not Present):	N/A	
Compartment 1 Scum accumulation (Inches, if other specify):	6	
Compartment 1 Sludge accumulation (Inches, if other specify):	4	
Pumping needed:	NO	
Approximate Gallons to be pumped (if needed) by Certified Pumper:	1000	

Distribution: D-Box

This component was:	Not Inspected	
D-Box in good condition:		
D-Box outlets set to allow equal effluent distribution:		

Drainfield: Gravity

This component was:	Partially Inspected	
Component appears to be functioning as intended:	YES	
Ponding present? If YES explain in comments:	NO	